

Fig. 1a
(PRIOR ART)




Fig. 1b
(PRIOR ART)




Fig. 2a
(PRIOR ART)




Fig. 2b
(PRIOR ART)




Fig. 2c
(PRIOR ART)




Fig. 3
(PRIOR ART)









Fig. 4






$$H_X = 0$$

Fig. 8a



$$H_X = 0.25H_C$$

Fig. 8b



$$H_X = 0.50H_C$$

Fig. 8c




Fig. 9a




Fig. 9b



Fig. 10a




Fig. 10b




Fig. 10c



Fig. 10d




Fig. 11